



Part Number: TY1542-50

Part Description: Lower Locking Actuator

Specifications

Product Families:	Accessories
Product Group:	Engine Systems Accesories
Part Number	TY1542-50
Root Part Number	TY1542-50
ATA Chapter 2 Digit	78
ATA Chapter 4 Digit	78-32
ATA Chapter 6 Digit	78-32-43
MFR / Manufacture -CAGE Code	Goodrich
Application	V2500

Repair

Part Number	TY1542-50
Description	Lower Locking Actuator
Repair Manual- CMM	CMM
Bench Check & Advise	Yes
Repair	Yes
Overhaul	Yes
Repair Facility	Hialeah

Logistics

Part Number	TY1542-50
Description	Lower Locking Actuator

From sophisticated composite repairs for nacelles and stabilizers to intricate nose-to-tail flight control overhaul, 630 Aerospace offers a full range of services and payment approaches that accommodates each customer's mission requirements, business needs, and financial goals.

630 Aerospace where quality is built in not inspected.



Copyright 2021. 630 Aerospace Inc.

customerservice @630aerospace.com | +1-754-208-3737